FREE Software Update for Subaru® vehicles
ADS255 - Code D747856AD

July 2017



Subaru® 'G' type keys can be rapidly identified thanks to the letter engraved on the blade.

Advanced Diagnostics is pleased to announce the release of a free update for Subaru® 2016 ADS255 software. The new update allows 'G' keys to be programmed in a lost key situation for various Subaru® vehicles without requiring a pincode.

What does the software update do?

ADS255 programs keys for late model Subaru® vehicles with bladed ('G' key type) ignitions without the need of an existing key. (Vehicles with proximity keys require a working key).

The software also covers remote (RKE) programming and is designed to be very fast and easy to use. A maximum of 4 keys / remotes can be programmed.

What other software and products will I need?

MVP PRO / AD100 PRO

A or SMART DONGLE

ADS228 SOFTWARE



Contact your distributor to buy ADS255 software now.

OFFER DETAILS	
Cable	ADC250 or ADC251
Dongle	A or Smart Dongle
Software category	C
Other software required	ADS228
Smart card	Yes - or Smart Dongle

® All the brands and product names mentioned in this flyer are registered trademarks exclusive property of authorized manufacturers. Said trademarks or trade names are nominated only for the purposes of information in order to be rapidly identified.

www.silca.biz - www.silca-automotive.com - www.advanced-diagnostics.com

SILCA S.p.A. Via Podgora, 20 (Z.I.) - 31029 Vittorio Veneto (TV) - Italy - Telephone +39 0438 9136 Fax +39 0438 913800

Software update applications

Subaru® ADS255

TABLE

			PIN	PIN	PRO				REF.
Forester (Blade) 2012 to 2016	✓	✓	✗	✗	ADC250 or ADC251	A or Smart Dongle	✗	ID6E-17	TOY43TE
Impreza (Blade) 2013 to 2016	✓	✓	✗	✗	ADC250 or ADC251	A or Smart Dongle	✗	ID6E-17	TOY43TE
Outback (Blade) 2015 to 2016	✓	✓	✗	✗	ADC250 or ADC251	A or Smart Dongle	✗	ID6E-17	TOY43TE
WRX (Blade) 2014 to 2016	✓	✓	✗	✗	ADC250 or ADC251	A or Smart Dongle	✗	ID6E-17	TOY43TE
XV (Blade) 2013 to 2016	✓	✓	✗	✗	ADC250 or ADC251	A or Smart Dongle	✗	ID6E-17	TOY43TE

Important Note: To Prevent damage to the Smart Dongle, ensure that the ignition is turned off when connecting the tester to the vehicle.

® All the brands and product names mentioned in this flyer are registered trademarks exclusive property of authorized manufacturers. Said trademarks or trade names are nominated only for the purposes of information in order to be rapidly identified.

07/2017

SILCA S.p.A. Via Podgora, 20 (Z.I.) - 31029 Vittorio Veneto (TV) - Italy - Telephone +39 0438 9136 Fax +39 0438 913800